



# Making a Radar



(S) : short  
(M) : middle  
(L) : long



## 1






## 2




## 3




4





-  X 1
-  (S) X 1
-  X 1



5




6

-  (M) X 1
-  X 1
-  X 1
-  X 1








7

Assemble to match the large gear and small gear.









8

-  (M) X 1
-  (L) X 1
-  (S) X 1
-  X 1






9

-  X 2
-  X 4
-  (L) X 2
-  (S) X 2
-  X 4



10

-  X 1
-  (L) X 2
-  X 2




11



12

 X 1

 X 2





13

 X 2


 X 1

 (L) X 1

 (S) X 1




14

 (S) X 1


 X 1

 X 1



15

 X 1



 (S) X 1


 X 1






16

-  X1
-  (S) X1







17

-  (M) X2
-  X1
-  X1
-  X1












18

-  (L) X1
-  (S) X1
-  X1



19

-  X2
-  X1
-  X4
-  (L) X4
-  (S) X2
-  X6
-  X1
-  X2



20

 X 2

 X 2

 X 1

 (S) X 2



21




DC motor X 1



22

 X 2

 X 2

 (S) X 2



23



X 2



Motor axis X 2




24



X 1



X 1




25



X 1




26




X 1





X 2



27









# Part List of a Radar

