



Making a Drawbridge

1



(S) : short
(M) : middle
(L) : long



X 1




X 2



X 2



X 2




2



X 2



X 1




3



DC Motor X 1




X 4



4

(S) X 2



5


(S) X 1

Motor axis X 1

(L) X 1

X 1

X 1




6

X 2

X 1

(S) X 2



7

X 2

X 1

X 2

X 2

(대) X 4

X 4




8



X 2



X 1



X 2



X 2



9





X 1



(L) X 2




X 2




10



(S) X 2




11



X 1




X 2




(L) X 2







X 2






12



13






14



Assemble to the match the large and small gears

15




16

300000C X 1

600000B X 2

(S) X 2




17

(M) X 1

X 1

X 1

(L) X 1




Assemble to the match the large and small gears

18

(M) X 1


X 1

X 2




19

(S) X 2



Assemble the opposite side as same

20



X1




X2



X2



X2




21



X2



X1



22




X2



(L) X2



X2



23




X2



X1




(L) X2






(S) X2




X2









24

-  X 2
-  X 1
-  X 2





25

-  X 2
-  X 1
-  X 2
-  X 2
-  X 4
-  X 4







26

-  X 2
-  X 1





27

-  X 1
-  X 2
-  X 2





28

 (S) X 2



29

 (S) X 2




Assemble the opposite side as same


30


 (S) X 1




Do not assemble strongly.
The link frame must to be sliding.




31

 Remote sensor X 1






Open the bridge



To open or close the bridge, use these buttons.

Part List of a Drawbridge



X 3



X 4



X 4



X 4



X 6



X 8



X 8



X 4



X 5



X 6



X 6



X 1



X 2



X 4



X 4




X 2




X 3



X 3




(L) X 20




(S) X 21




X 20




(M) X 6



(S) X 1



(L) X 2




(S) X 2



X 6



X 4



Remote sensor X 1



Motor axis X 1



DC motor X 1

