





Making a Line tracer


1



2




3



4

X 2




5

X 2

(long) X 2


X 2



6

(long) X 2

X 2




7

X 2


(long) X 2

X 2




8

X 2



9

X 1



10


X 2

X 2


X 4

(short) X 2

X 6




11



12

IR sensor X 3







13

X 1





















END



Part List of a Line tracer

 X 1  X 2 <p>1</p>	 X 2  X 2  (long) X 2 <p>2</p>	 X 1 <p>3</p>	 X 2 <p>4</p>	 X 2  (long) X 2  X 2 <p>5</p>
 (long) X 2  X 2 <p>6</p>	 X 2  (long) X 2  X 2 <p>7</p>	 X 2 <p>8</p>	 X 1 <p>9</p>	 X 2  (short) X 2  X 2  X 6  X 4 <p>10</p>
<p>11</p>	 X 3 <p>12</p>	 X 1 <p>13</p>	<p>14</p>	<p>15</p>

 X 1 <p>1</p>	 X 2  X 1 <p>X 1</p>	 X 2  X 2 <p>X 2</p>	 X 2  X 2 <p>X 2</p>	 X 2  X 4  X 3 <p>X 3</p>	 X 2  X 2 <p>X 2</p>	 (long) X 6  (short) X 2  X 2  X 6  (long) X 2  X 6 <p>X 6</p>
---	--	--	---	--	--	--

Total Part List